



23	KA1	Slave relay	1	MCAN		11	QP1	Auto-switch	1	CASV 16A	No.	Mark	Name	Qty	Model	Note
24	Q1	Finger Switch	1	JCH13		12	QP2	Auto-switch	1	CASV 6A			DP1	1	406L	
25	YA1	magnet	1	MB1-25		13	QP3	Auto-switch	1	CASV 6A			VCI	1	0UT-24V	0.7A
26	SB1	Button	1	FA131		14	QP4	Auto-switch	2	CASV 6A			V1	1	Inverter	Hor-t-Inverter
27	SB2	Button	1	EM2462		15	QP5	Auto-switch	2	CASV 6A			V2	1	Inverter	Hor-t-Inverter
28	SB3	Button	1	EA121		16	RP1	potentiometer	1	2.2K $\Omega$			T1	1	temperature meter	Hor-t-temperature meter
29	SB4	Button	1	EA542	red mushroom shape	17	E1	Hor-t-switch	1	MNSV-P7			T2	1	temperature meter	Hor-t-temperature meter
30	M3	fan-motor	1	220V 25W		18	E2	Hor-t-approach	1				T3	1	temperature meter	Mid-temperature meter
31	M2	Mid-motor	1	220V 550W		19	E3	Mid-seal switch	1				T4	1	temperature meter	Mid-temperature meter
32	M1	Hor-t-motor	1	220V 750W	4 Level	20	E4	sensor	1	E3S-NSHF4			T5	1	temperature meter	Hor-t-temperature meter
33	ST1	thermocouple	1	CA-3	0.5m straight butt	21	E4	heater pipe	2	220V_350W			T6	1	temperature meter	Hor-t-temperature meter
34	ST2	thermocouple	1	CA-3	0.5m straight butt	22	E4	heater pipe	2	220V_350W			T7	1	temperature meter	Hor-t-temperature meter